

General Environmental Incident Summary

Incident: 4052 **Date/Time Notice:** 3/25/2016 1915 **DEM Incident No:**
Responsible Party: Canaan Mountain LLC.
Date Incident: 3/25/2016 **Time Incident:** 1910 **Duration:** 4 hours
County: Dunn **Twp:** 149 **Rng:** 95 **Sec:** 33 **Qtr:**
Lat: 47.68000 **Long:** -102.83000 **Method:** Navigation quality GPS
Location Description: From HWY 73 go south on county road 53 about 11 miles, truck and trailer rolled on SW side of HWY

Submitted By: Scott Daniels **Affiliation:**
Address: PO box 781
City: New Town **State:** ND **Zip:** 58763

Received By:

Contact Person: Ray Jessop
2783 S Shilo Rd
Apple Valley, UT 84737

Distance Nearest Occupied Building: 1 Miles **Release Contained:** Yes

Type of Incident: Vehicle Accident

Description of Released Contaminant: Salt Water

Volume Spilled: 20.00 barrels **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

Glare of the sun in drivers eyes, dirty windshield from bugs and other debris, driver was possibly going to fast

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Soil was contaminated by salt water, contaminated soil was removed and replaced with new top soil so no impacts

Action Taken or Planned:

Water was immediately sucked off tanker that was wrecked, water was sucked out of the area that was affected by any water getting on ground, all debris was cleaned up from wreck and properly disposed of. Truck and trailer were removed from wreck scene by wrecker, stripping dirt 2.5 feet down with a backhoe entire area affected. Hauling in 48 yards of top soil to replace contaminated soil. Future action would be to make sure all windows were clean and there was no obstruction of view and driver slow down to see the road better.

Wastes Disposal Location: Secure Disposal in Keene, ND

Agencies Involved: State Highway Patrol, Local Fire Department, Local Law Enforcement, Local Emergency Manager

Updates

Date: 3/25/2016 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Volume:

Notes:

According to the incident summary, this spill impacted areas not associated with an E & P location. Follow-up is necessary.

Date: 3/28/2016 **Status:** Inspection

Author: Crowdus, Kory

Updated Volume:

Notes:

On location 3/28/2016, at 12:05 p.m. Met with contact person at site and was informed salt water was sucked up, and impacted soils were excavated and taken for disposal. Impacted area at site of rollover is approximately 15 x 80 ft, and area has been scraped. Release then flowed to the south in a path approximately 4 x 200 ft. A conductivity probe was used at the rollover site and within the flow path. There were no elevated levels compared to the background levels in the area. No remaining impacts seen at this time. Further follow-up is required to check on vegetation growth.

Date: 4/7/2016 **Status:** Correspondence

Author: Martin, Russell

Updated Volume:

Notes:

Received results of samples taken by responsible party. All results are below NDDoH action levels.